

Under Review Notification

Raised By: VANESSA MOREL

Product #: DART TOOLING EUROCOPTER / H175

Date: 17.11.21

Product Name: MLG TRAILING ARM REPLACEMENT

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		HOLD SHIPMENT	Red Tag/Quarantine Stock	Advise Customers	Stop Production	Re-Work Stock	IPP Under Review	Product Specifications Under Review ("Bluefiles")		
RBEM323V3009101-3	RBEM323V3009101 REV 1	N	Y	N	N	Y	Y	Y	17-755	REWORK STOCK IF APPLICABLE
RBEM323V3009101-7	RBEM323V3009101 REV 1	N	Y	N	N	Y	Y	Y	17-755	REWORK STOCK IF APPLICABLE
RBEM323V3009101-5	RBEM323V3009101 REV 1	N	Y	N	N	Y	Y	Y	17-755	REWORK STOCK IF APPLICABLE

Description of Issue: FABRICATION PROBLEM

RBEM323V3009101-3 REV B: -49 ASSY ADDED FOR HELICAL INSERT
 RBEM323V3009101-7 REV B: TAP FOR 5/16-18 HELICAL INSERT (2 HOLES)
 RBEM323V3009101-5 REV B: C'SINK FOR 5/16-18 BOLT (2 HOLES)

Distribution:

VP Operations Director of Operations Director Quality Assurance Director of Engineering	Chief Engineer Engineering Project Managers Engineering Clerk Customer Support Manager	Production Engineers Production Planners Purchasing Manager Technical Support	Product Manager - Solutions Provider
--	---	--	--------------------------------------